CMHC SCHL

Helping to house Canadians



Canada

BIBLIOGRAPHY ON VENTILATION/
BIBLIOGRAPHIE SUR LA VENTILATION

BIBLIOGRAPHY ON VENTILATION/BIBLIOGRAPHIE SUR LA VENTILATION

TH 7225 A54 — Air Conditioning Contractors of America. Environmental Systems for Existing Residences. Washington: Air Conditioning Contractors of America, 1979.

TH 7225 A58 — _____. Selection of Distribution System. Washington: Air Conditioning Contractors of America, 1963.

Per. — Air Infiltration and Ventilation Centre. Recent Additions to AIRBASE. Bracknell, Berkshire: The Centre, 1980-.

Cal MH 88A37 — Air-Ins, Inc. Air Permeance of Building Materials: Summary Report. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH 88A37f — _____. Perméance des matériaux de construction à l'air: rapport succinct. Ottawa: Société canadienne d'hypothèques et de logement, 1988.

TH 7005 A38 1980 — Air Infiltration Centre Conference (1st: 1980: Windsor Great Park; Berkshire, Eng.). Air Infiltration Instrumentation and Measuring Techniques: Proceedings, 1st AIC Conference. Document AIC-PROC-1-80. Bracknell, Berkshire: Air Infiltration Centre, 1981.

TH 7005 A38 1981 — _____. (2nd: 1981: Royal Institute of Technology, Stockholm). Building Design for Minimum Air Infiltration: 2nd AIC Conference, held at Royal Institute of Technology, Stockholm, Sweden, 21-23 September 1981: Proceedings. St. Albany, England: Oscar Faber Partnership, 1982.

Per. — Air Infiltration Review. Bracknell, Berkshire: Air Infiltration Centre, 1979-

TD 883.14 A4 1985 — Air Quality: Ventilation, Hazardous Gas, and Radon Contaminants: A Collection of Papers from the ASHRAE Annual Meeting at Honolulu, Hawaii, June 1985. ASHRAE Technical Data Bulletin, v.1, no.1. Atlanta, Ga.: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1985.

Ca2 AL M10 86V29 — Alberta. Energy Conservation Branch. Ventilating Your Home. Edmonton: The Branch, Alberta Energy and Natural Resources, 1986.

TH 7015 T36 no.5 — Allen, Carolyn. AIRGLOSS: Air Infiltration Glossary. Technical Note AIC-TN-5-81. Bracknell, Eng.: Air Infiltration Centre, 1981.

TH 7015 T36 no. 5.1. — _____. AIRGLOSS: Air Infiltration Glossary (English-German/ Deutsch-Englisch). Supplement. Technical Note AIC-TN-5-1-83. Bracknell, Berkshire: Air Infiltration Centre, 1983.

TH 7015 T36 no.5.4 — _____. AIRGLOSS: Air Infiltration Glossary (English-Dutch/Nederlands-Engels) Supplement. Technical Note AIVC: 5-4-88. Bracknell, Berkshire: Air Infiltration and Ventilation Centre, 1988.

TH 7015 T36 no.6 — _____. Reporting Format for the Measurement of Air Infiltration in Buildings. Technical note; AIC-TN6-81. Bracknell, Eng.: Air Infiltration Centre, 1981.

TH 4816 A43 1984 — Amélioration de l'habitat existant: procédés et produits. Réalisé par le Centre d'assistance technique et de documentation avec le concours de l'Agence nationale pour l'amélioration de l'habitat. Paris : Publications du Moniteur, 1984.

TH 7011 A4 — American Society of Heating, Refrigerating and Air-Conditioning Engineers. ASHRAE Handbook & Product Directory. New York: The Society, 1973-

TH 7201 A8 — _____. ASHRAE Handbook. Fundamentals. Atlanta, Ga.: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1981-.

TH 7201 A803 1987 _____. ASHRAE Handbook. Heating, Ventilating and Air-conditioning. Atlanta, Ga: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1987-.

TH 7201 A805 _____. ASHRAE Handbook. Systems. Atlanta, Ga.: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1984-.

TH 7201 A815 _____. ASHRAE Transactions. Atlanta, Ga.: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1959-.

TH 7011 T47 1986 _____. Terminology of Heating, Ventilation, Air Conditioning, and Refrigeration. Atlanta, Ga.: American Society of Heating, Refrigerating, and Air-Conditioning Engineers, 1986.

TH 7653 V46 1986 _____. Ventilation for Acceptable Indoor Air Quality. ASHRAE Standard 62-1981R. Atlanta, Ga.: American Society of Heating, Refrigerating, and Air-Conditioning Engineers, 1986.

TH 7406 F56 1988 Ashton and Associates Limited. Flue Gas Spillage: Status of Technology Transfer: Final Project Report. Prepared for Canada Mortgage and Housing Corporation. Ottawa: Ashton and Associates Limited, 1988.

Cal MH42 85F32 Balanced Energy Systems Technology Inc. Field Evaluation of Residential Ventilation Systems Guidelines: Final Report. Prepared for the Policy Development and Research Sector of Canada Mortgage and Housing Corporation. Ottawa: The Corporation, 1985.

Cal RC64 79N49 Beach, R.K. Relative Tightness of New Housing in the Ottawa Area. Building Research Note no. 149. Ottawa: Division of Building Research, National Research Council of Canada, 1979.

Cal MH 88T21 Brown, W.C. Testing of Air Barrier Systems for Wood Frame Walls: Client Report. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH110 89A71 — Buchan, Lawton, Parent Ltd. Attic Air Change Testing: Protocol Development: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1989.

Cal MH 86E87 — _____. Evaluation of the Potential for Fuel-Fired Appliance Backdraft in Ten Houses Equipped with Whole-House Exhaust Fans. Ottawa: Canada Mortgage and Housing Corporation, 1986.

Cal MH110 89I55 — _____. Improved Make-Up Air Supply Techniques: A Report. Ottawa: Canada Mortgage and Housing Corporation, 1989.

Cal MH 86V21 — _____. Ventilation Alternatives for Maritime Houses: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1986.

Cal MH110 87R21 — Buchan, Lawton, Parent Ltd. and SRO Engineering. Residential Combustion Spillage Monitoring. Ottawa: Canada Mortgage and Housing Corporation, 1987.

TH 7005 B8 1978 — Building Air Change Rate and Infiltration Measurements: A Symposium. Sponsored by ASTM Committee E-6 on Performance of Building Constructions, American Society for Testing and Materials, Washington, D.C., 13 March 1978. C.M. Hunt, J.C. King, and H.R. Trechsel, editors. ASTM Special Technical Publications; 719. Philadelphia, Pa.: American Society for Testing and Materials, 1980.

KF 5701 A73B83 — Building Officials and Code Administrators International. The BOCA National Mechanical Code. Country Club Hills, Ill.: Building Officials and Code Administrators International, 1987-.

Cal MH 89I55 — Bumbaru, Doru. Air Permeance of Building Materials. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH166 79C58 — CMHC Industry/Science Seminar, Ottawa, 1978. Controlled Ventilation with Exhaust Air Heat Recovery for Canadian Housing: Proceedings. Ottawa: CMHC, Research and Development Division, Professional Standards and Technology Directorate, 1979.

Cal MH42 85F32a — Canada Mortgage and Housing Corporation. Field Evaluation of Residential Ventilation Systems Guidelines: Appendices. Ottawa: Policy Development and Research Sector, The Corporation, 1985.

Cal MH 87M51 — _____. Moisture and Air: Problems and Remedies. Ottawa: The Corporation, 1987.

Cal MH 86V23 — _____. Ventilation: Health and Safety Issues: Problems, Causes and Solutions. Ottawa: The Corporation, 1986.

Cal MH110 90E25 — Canet Research Inc. The Effectiveness of Low-Cost Continuous Ventilation Systems. Ottawa: Canada Mortgage and Housing Corporation, 1990.

SW5 BR20 80D37 — Carlsson, Bjorn; Elmroth, Arne and Engvall, Per-Ake. Airtightness and Thermal Insulation: Building Design Solutions. D37: 1980. Stockholm: Swedish Council for Building Research, 1980.

TH 7015 C47 1988 — Charlesworth, Peter. Air Exchange Rate and Airtightness Measurement Techniques: An Applications Guide. Coventry, Great Britain: Air Infiltration and Ventilation Centre, 1988.

Ca2 ON EP80 81H78 — Ciz, J.B. and Jones, W.R. Humidity Ventilator: Design and Preliminary Performance Evaluation. Toronto: Ontario Hydro, Research Division, 1981.

TH 7341 D4 — Cole, James T., et al. Development and Field Verification of a Model of Excess Infiltration and House Air Infiltration for Single-Family Residences: Final Report for 1979. Springfield, Va.: National Technical Information Service, U.S. Dept. of Commerce, 1980.

Cal RE59 C13 1977f — Conseil national de recherches du Canada. Comité associé du Code national du bâtiment. Code canadien du chauffage, de la ventilation et du conditionnement d'air, 1977. CNRC no. 15560f. Ottawa: Conseil national de recherches du Canada, 1977.

Cal RE59 C13 1977f Sup. _____. Comité associé du Code national du bâtiment. Équivalents métriques des unités anglaises utilisées dans le Code canadien du chauffage, de la ventilation et du conditionnement d'air, 1977. CNRC no. 15560F-M. Ottawa: Conseil national de recherches du Canada, 1977.

Cal RC54 80P03 Construction Details for Air Tightness: Record of the DBR Seminar/Workshop, October, November 1977 and January 1978. Proceedings no.3 of the Division of Building Research. Ottawa: National Research Council of Canada, Division of Building Research, 1980.

TH 7684 D9C67 1984 Corbett, Robert and Miller, Barbara. Infiltration Control: The Air-Vapor Barrier. Butte, Mt.: National Center for Appropriate Technology, 1984.

TH 7226 C7 Crall, G. Christopher P. Bibliography on Available Computer Programs in the General Area of Heating, Refrigerating, Air Conditioning and Ventilating. American Society of Heating, Refrigerating, and Air-Conditioning Engineers. New York: The Society, 1975.

TH 7687 C7 1981 V.1 Croome, Derek J. and Roberts, Brian M. Airconditioning and Ventilation of Buildings. International Series in Heating, Ventilation and Refrigeration: v. 14. Oxford, England; Toronto: Pergamon Press, 1981.

TH 7341 D5 Dickson, D.J. Air Flow Through and Within Masonry Walls. ECRC/M1420. Capenhurst, Chester: Electricity Council Research Centre, 1981.

TH 7341 D52 _____. Methods of Measuring Ventilation Rates and Leakage of Houses. ECRC/M1419. Capenhurst, Chester: Electricity Council Research Centre, 1981.

Cal RC61a 86P1383 Dumont, R.S. The Effect of Mechanical Ventilation on Rn, NO_2 and CH_2O Concentrations in Low-Leakage Houses and a Simple Remedial Measure for Reducing Rn Concentration. IRC Paper no. 1383. Ottawa: National Research Council Canada, Institute for Research in Construction, 1986.

SW5 BR20 78D10 Elmroth, Arne. Well Insulated Airtight Buildings: Design and Construction. Document: D10: 1978. Stockholm: Swedish Council for Building Research, 1978.

SW5 BR20 83D02 Elmroth, Arne and Levin, Per. Air Infiltration Control in Housing: A Guide to International Practice. Stockholm: Swedish Council for Building Research, 1983.

Cal MT259 83R10 Engineering Interface Ltd. Testing of Air Leakage and Combustion Efficiency in Rooftop HVAC Units: A Research Report. Prepared under a subcontract from the Centre for Building Studies, Concordia University. BETT Publication no. 83.10. Ottawa: Buildings Energy Technology Transfer Program, Energy, Mines and Resources Canada, 1983.

Cal MH 88N58 Fergusen, Simek, Clark, Engineers and Architects. Northern Ventilation Project: Data Collection and Report for Iqualuit, N.W.T. Ottawa: Canada Mortgage and Housing Corporation, 1988.

TH 7015 T36 no.29 Feustel, Helmut E. Fundamentals of the Multizone Air Flow Model: COMIS. Coventry, Great Britain: Air Infiltration and Ventilation Centre, 1990.

Cal MH 85I51 G.K. Yuill and Associates. The Investigation of Backdrafting at 200 Linacre Road in Winnipeg. Ottawa: Canada Mortgage and Housing Corporation, 1985.

Cal MH 87I53 _____. Investigation of the Indoor Air Quality, Airtightness, and Air Infiltration Rates of a Statistically Random Sample of 78 Houses in Winnipeg. Ottawa: Canada Mortgage and Housing Corporation, 1987.

Cal MH65 89P61 _____. Project to Continuously Monitor the Performance of the Laminar Air Flow Super Window - Humidity Controlled Air Inlet - Baseboard Heater Ventilation and Heating System: Report for Canada Mortgage and Housing Corporation. Ottawa: The Corporation, 1989.

RA 575.5 I53 1985 Gammage, Richard B., et al., editors. Indoor Air and Human Health. Chelsea, Mi.: Lewis Publishers, 1985.

US1 DE82 72T05 Garrivier, P. Use of an Air-to-Air Exchanger to Recover Heat from Air Exhausted by Mechanical Ventilation. NBS Technical Note; no. 710-5. Washington, D.C.: U.S. Dept. of Commerce, National Bureau of Standards, 1972.

TH 7015 G5 Giesbrecht, Peter. An Abstract on Air Tightness in Homes. Edited by Lawrie Shearer. Winnipeg: Ener-Corp Management, 1982.

US1 EM30 81I55 Grimsrud, D. T.; Sonderegger, R.C. and Sherman, M.H. Infiltration Measurements in Audit and Retrofit Programs. Presented at the International Energy Agency (IEA) Energy Audit Workshop, Elsinore, Denmark, April 13-15, 1981. D.T. Grimsrud, R.C. Sonderegger and M.H. Sherman, Energy and Environment Division, Lawrence Berkeley Laboratory, University of California. Washington: Office of Buildings and Community Systems, Dept. of Energy; Springfield, Va.: National Technical Information Service, 1981.

USI EM 78I56 Grimsrud, D.T., et al. Infiltration-Pressurization Correlations: Detailed Measurements on a California House. Berkely, Ca.: Energy and Environment Division, Lawrence Berkely Laboratory, University of California; Springfield, Va.: National Technical Information Service, 1978.

Cal MH110 88R22 HRAI Technical Services Division, Inc., and Energy Systems Centre, Ontario Research Foundation. Residential Exhaust Equipment: A Research Report. Ottawa: Canada Mortgage and Housing Corporation, 1988.

TH 7657 H35 1985 Hamilton, Gavin and Kew, John. Negative Air Ionisation in Buildings. Technical Note; TN 85/4. Bracknell, Berkshire: Building Services Research and Information Association, 1985.

Cal MH110 90V25 Hamlin, Tom; Forman, John; and Lubun, Mike. Ventilation and Airtightness in New, Detached Canadian Housing. Ottawa: Canada Mortgage and Housing Corporation, 1990.

SW5
BR20
79D10

Handa, Kamal. Wind Induced Natural Ventilation. Document; D10: 1979. Stockholm: Swedish Council for Building Research, 1979.

Audio
Cal
RC51
82H71

Handegord, G.O. Humidity, Condensation and Ventilation in Housing. Kit. Produced by B.F. Stafford. Ottawa: National Research Council of Canada, Division of Building Research, 1982.

Cal
RC64
79N51

_____. The Need for Improved Air Tightness in Buildings. Building Research Note; no. 151. Ottawa: National Research Council, Division of Building Research, 1979.

TH
7425
H37
1983.

Hatzinikolas, Michael. Fresh Air Intake for Fireplaces. A.M.I./ Alberta Masonry Institute; no. 23. Edmonton: Alberta Masonry Institute, 1983.

Cal
RD36
84T07

Hawken, P.J. A Comparison of Ventilation Strategies for Tightly Constructed Houses in Cold Climates = Étude comparative de techniques de ventilation pour maisons étanches à l'air dans des climats froids. Technical Report (Low Temperature Laboratory) no. TRLT-007. Ottawa: National Research Council Canada, Division of Mechanical Engineering, 1984.

TH
7684
D9R46
1986

Heating, Refrigerating and Air Conditioning Institute of Canada. Residential Air System Design Manual. Islington, Ont.: The Institute, 1986.

TH
7392
C65
H4
1981

Henderson, John K.; Hartnett, William J. and Shatkun, Phil. The Handbook of HVAC Systems for Commercial Buildings. Edited by Leroy Varner and Technical Consultants, Inc.: Prepared for publication by Cheryl J. Miller. Washington: Building Owners and Managers Association, 1981.

Cal
RC54
84P07

Humidity, Condensation and Ventilation in Houses: Proceedings of the Building Science Insight '83, October, November and December 1983. National Research Council of Canada, Division of Building Research. Proceedings of the Division of Building Research; no.7. Ottawa: National Research Council Canada, 1984.

TD 883.1 I4 1985 — Indoor Air Quality and Conservation: Putting the Problem in Perspective. Sponsored by Washington Energy Extension Service and Oregon State University Extension Energy Program, November 15-16, 1984, Bellevue, Washington. Seattle: Energy Business Association, 1985.

TH 7005 I53 1985 — Infiltration and Air Leakage: A Collection of Papers from the ASHRAE annual meeting at Honolulu, Hawaii, June 1985. Atlanta, Ga.: American Society of Heating, Refrigerating and Air-Conditioning Engineers, 1985.

SW5 BR10 89R55 — Johansson, Geron. Reglerutrustning for balanserad ventilation. Stockholm, Sweden: Statens rad for byggnadsforskning, 1989.

TH 7684 D9K32 1988 — Kadulski, Richard. Residential Ventilation: Achieving Indoor Air Quality. North Vancouver, B.C.: Drawing-Room Graphic Services, 1988.

TH 7653 K37 — Karulak, Janusz. Air Exchange in Multi-Storey Buildings. London: s.n., 197--

TH 7335 K48 — Khashab, A.M. Heating, Ventilating, and Air-conditioning Systems Estimating Manual. New York: McGraw-Hill, 1977.

TH 7684 D9K53 1985 — Kiel, Darwin Edward. Measuring and Modelling Air Flow Through Doorways. Thesis (M.Sc.) - University of Alberta, 1985.

Cal MH110 82E84 — Knight, J. The Evaluation of the "No-Wind" Airtightness of the Apple Hill Homes. Prepared by Retrospectors, Research and Consulting. Principal Consultant: J. Knight. Ottawa: Canada Mortgage and Housing Corporation, 1982.

TH 7015 T36 no.21 — Knight, Paul A. Mechanical Systems Retrofit Manual: A Guide for Residential Design. New York: Van Nostrand Reinhold Co., 1987.

SW5 BR20 80D08 Kronvall, Johnny. Airtightness: Measurements and Measurement Methods. Document; D8: 1980. Stockholm: Swedish Council for Building Research, 1980.

TD 883.1 K7 Krzaniak, Michael S. Infiltration, Energy Conservation and Indoor Air Quality. Ottawa: Carleton University, Dept. of Mechanical and Aeronautical Engineering, 19--

ZZ EM 85R22 Kvisgaard, Bjorn; Collet, P.F., and Kure, J. Research on Fresh-air Change Rate. 1, Occupants' Influence on Air-change. 2nd ed. Luxembourg: Commission of the European Communities, 1985.

USI EM30 81F32 Lawrence Berkely Laboratory, University of California. Find out and Fix the Leaks: A Guide to Air Infiltration Reduction and Indoor Air Quality Control. DOE/CE-006. Washington: U.S. Dept. of Energy, Assistant Secretary for Conservation and Renewable Energy, Office of Buildings and Community Systems, 1981.

TH 7015 L4 1982 Lee, H.S. A Field Study of Natural Ventilation in Better Insulated Houses: Final Report. Edinburgh, Scotland: Heriot-Watt University, Dept. of Building, 1982.

TH 7015 L5 1986 Liddament, Martin. Air Infiltration Calculation Techniques: An Applications Guide. Bracknell, Berkshire: Air Infiltration and Ventilation Centre, 1986.

TH 7653 L52 1986 _____. Building Airtightness and Ventilation: An Overview of International Practices. Bracknell, Berkshire: Building Services Research and Information Association, 1986.

TH 7015 T36 no.21 _____. A Review and Bibliography of Ventilation Effectiveness: Definitions, Measurement, Design and Calculation. Bracknell, Berkshire: Air Infiltration and Ventilation Centre, 1987.

TH 7015 T36 no.7 _____. 1981 Survey of Current Research Into Air Infiltration in Buildings. Technical Note AIC-TN-7-81. Bracknell, Berkshire: Air Infiltration Centre, 1981.

Cal RD36 86T04 Linton, J.W. A Comparison of Ventilation Strategies for R-2000 Houses = Étude comparative de techniques de ventilation pour maison R-2000. Technical Report (Low Temperature Laboratory); TR-LT-004. Ottawa: National Research Council Canada, Division of Mechanical Engineering, 1986.

TH 7684 D9 L57 Lischkoff, James K. and Lstiburek, Joseph. The Airtight House: Using the Airtight Drywall Approach: A Construction Manual. Iowa: Iowa State University Research Foundation, 1986.

Cal MH 86A37 Love, J.A. Airtightness Testing Methods for Multi-Unit Housing. Ottawa: Canada Mortgage and Housing Corporation, 1986.

Ca2 AL H050 85A34 Love, J.A. and Passmore, R.S. Air Leakage in Existing Iowa Houses. Edmonton: Innovative Housing Grants Program, Alberta Dept. of Housing, 1985.

Ca2 AL H050 85C52 Lstiburek, Joseph W. Construction Experience Using the Airtight Drywall Approach. Edmonton: Alberta Dept. of Housing, Innovative Housing Grants Program, 1985.

SW5 IB12 83B23 Lyrberg, Mats D. Models of Infiltration and Natural Ventilation. Gavle, Sweden: National Swedish Institute for Building Research, 1983.

SW5 IB12 83B21 _____. Residents and Windows. 2, Airing. Gavle, Sweden: National Swedish Institute for Building Research, 1983.

TH 7653 M34 Makowlecki, Jerzy. Problems of Effective Space Ventilation. HVRA Translation; 217. London: Heating and Ventilating Research Association, 197—

Cal MT258 84A37 Marbek Resource Consultants. Air Sealing Homes for Energy Conservation. Prepared under a sub-contract from the Saskatchewan Research Council. 2nd draft. Ottawa: Energy, Mines and Resources Canada, 1984.

Cal MT258 84A37f ———. Étanchéisation des maisons aux fins de l'économie d'énergie. Par Marbek Resource Consultants, sous traitant du Saskatchewan Research Council. 2e version. Ottawa: Énergie, mines et ressources Canada, c1984.

Cal MH 88S78 Mattock, Chris. A Survey of Ventilation Systems for New Housing. Produced by Habitat Design and Consulting Ltd. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MT259 85R01 Mayo, Timothy. Combustion Air Supply Codes in Housing: A Research Report. Sponsored by the Energy Conservation Branch, Energy, Mines and Resources Canada; prepared by Timothy Mayo under a subcontract from TES Engineering Ltd. BETT publication: no. 85.01. Ottawa: Buildings Energy Technology Transfer Program, Energy Mines and Resources Canada, 1985.

TH 7656 M3 1985 McDermott, Henry J. Handbook of Ventilation for Contaminant Control. 2nd ed. Boston: Butterworth, 1985.

Ref. Z 6675 A33M38 1984 McLaughlin, W. Keith. Quality of Indoor Air and Health Effects of Indoor Air Pollution and Tight Building Syndrome. Occupational Health and Safety Bibliographic Series, no. 8. Edmonton: Occupational Health and Safety Library, Alberta Workers' Health, Safety and Compensation, 1984.

TH 7222 M26 1982 McQuiston, Faye C. and Parker, Jerald D. Heating, Ventilating and Air Conditioning: Analysis and Design. 2nd ed. New York; Toronto: Wiley, 1982.

TH 6025 M42 1986 Measured Air Leakage at Buildings: A Symposium. Sponsored by ASTM Committee E-6 on Performance of Building Constructions, Philadelphia, PA, 2-3 April 1984; Heinz R. Trechsel and Peter L. Lagus, editors. Special Technical Publication no. 904. Philadelphia, Pa.: ASTM, 1986.

TH 9031 C66 1988 — Merrill, John and Kathleen Parrott, editors. Condensation and Related Moisture Problems in the Home. Urbana-Champaign: American Association of Housing Educators and Small Homes Council - Building Research Council, University of Illinois at Urbana-Champaign, 1988.

Cal MH110 81A36 — Milne, W.C. Air Pressurization Test of Kanata Houses. Prepared for the Technical Research Division of Canada Mortgage and Housing Corporation by Scanada Consultants Ltd. Ottawa: CMHC, 1981.

TH 9115 N28 no. 90A — National Fire Protection Association. Technical Committee on Air Conditioning. Standard for the Installation of Air Conditioning and Ventilating Systems. NFPA-90A. Quincy, Mass.: NFPA, 1981.

Cal RE59 C13 1975 — National Research Council of Canada. Associate Committee on the National Building Code. Canadian Heating, Ventilating and Air-conditioning Code, 1975. Issued by the Associate Committee on the National Building Code, National Research Council of Canada. Ottawa: Associate Committee on the National Building Code, National Research Council of Canada, 1975.

Cal RE59 C13 1977 — _____. Associate Committee on the National Building Code. Canadian Heating, Ventilating and Air-conditioning Code, 1977. 2nd ed. Ottawa: Associate Committee on the National Building Code, National Research Council of Canada, 1977.

Cal RE59 C13 1977 Sup. — _____. Associate Committee on the National Building Code. Metric Values for Use with the Canadian Heating, Ventilating and Air-conditioning Code, 1977. Ottawa: Associate Committee on the National Building Code, National Research Council of Canada, 1977.

TH 6631 P58 1970 — National Research Council of Canada. Division of Building Research. Plumbing Venting in Experimental Houses: Mark IV & VI: A Study for the NHBA Technical Research Committee. Toronto: National House Builders Association, 1970.

Ca2 AL MA70 87H28 — Newton, Anthony John. Heating and Ventilating of Modern Housing. Edmonton: Alberta Municipal Affairs, Innovative Housing Grants Program, 1987.

TH
7222
N57
1987

Nisson, J.D. Ned. Residential Heating Systems. Arlington, Mass.: Cutter Information Corporation, 1987.

TH
7341
N9

Nylund, P.O. Air Leakage: A Neglected Feature in Energy Savings. S.l.: s.n., 1981.

SW5
BR20
80D22

_____. Infiltration and Ventilation. Document; D22: 1980. Stockholm: Swedish Council for Building Research, 1980.

Cal
MH65
86M22

Oboe Engineering Ltd. Medium Efficiency Filtration: Improved Filters for Residential Forced Air Furnaces. Ottawa: Project Implementation Division, Canada Mortgage and Housing Corporation, 1986.

Cal
MH
87R25

_____. Report on the Measurement of Air Leakage of the Test Wall Panels: Drying of Walls - Atlantic Canada. Ottawa: Canada Mortgage and Housing Corporation, 1987.

Ca2
ON
H085
81A91

Ontario Research Foundation. Aylmer Air Infiltration Study. A Housing Energy Management Program Report. Prepared for Ontario Ministry of Housing, Technical Services Division, Research & Development Section. Toronto: Ontario Ministry of Municipal Affairs and Housing, 1981.

Ref.
Z
5853
V4P37
1985

Parfitt, Yvette. Ventilation Strategy: A Selected Bibliography. Technical Note, AIC-TN-17-85. Bracknell, Berkshire: Air Infiltration Centre, 1985.

US1
EM115
84I51

Parker, G.B.; Wilfert, G.L. and Dennis, G.W. Indoor Air Quality and Infiltration in Multifamily Navy Housing. Richland, Wash.: Pacific Northwest Laboratory, 1984.

Ca2
ON
EP80
78D25

Perricone, F. Design of a Mechanical Ventilation System for Future Tightly Constructed Residential Homes. Report no: 78-411-K. Toronto: Ontario Hydro, Research Division, 1978.

Cal MH110 84I57 — Platts, R.E. Investigation of a Technique to Reduce Air Leakage in the Wall Cavities of Older Homes. Prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation by Scanada Consultants Limited; Principal consultant: R.E. Platts. Ottawa: the Corporation, 1984.

Cal PW22 88D37 — Public Works Canada. Measurement of Outdoor Air Supply Rate. Ottawa: Public Works, Architectural and Engineering Services, 1988.

Ca2 PQ ER50 85P52 — Québec (Prov.). Bureau des économies d'énergie. Les portes et les fenêtres: l'étanchéité. Québec: Le Bureau, 1985.

Ca2 PQ ER50 85V21 — _____. La ventilation. Québec: Le Bureau, 1985.

Cal MH 82U63 — Raab, Karl H. Updating Health Standards for Residential Construction. Ottawa: Canada Mortgage and Housing Corporation, 1982.

Cal MH 82U66 — _____. Upgrading Residential Forced Air Filtration. Ottawa: Canada Mortgage and Housing Corporation, 1982.

QD 181 R2I53 — Radon Information Council. Information Kit. Washington: The Council, 19—

US1 EM30 82R21 — Residential Air-Leakage and Indoor Air Quality in Rochester, New York. Prepared for New York State Energy Research and Development Authority, and U.S. Department of Energy, Assistant Secretary for Conservation and Renewable Energy Office of Buildings and Community Systems and Rochester Gas and Electric Corporation; prepared by Lawrence Berkeley Laboratory, F.J. Offerman... et al and Rochester Institute of Technology. ERDA Report 82-21. Berkeley, Calif.: Lawrence Berkeley Laboratory, University of California; Springfield, Va.: National Technical Information Service, 1982.

TH 7684 D9R49 — Resource Integration Systems Limited. Residential Gas Combustion Venting Issues Forum: Final Project Report. Toronto: Resource Integration Systems Limited, 1987.

TH 7683 F3R48 1984 — Revzan, K.L. Effectiveness of Local Ventilation in Removing Simulated Pollution from Point Sources. Berkeley, CA: Lawrence Berkeley Laboratory, Applied Science Division, 1984.

Cal MH 84H13 — Robinson, T.J. Hazardous Heating and Ventilating Conditions in Housing. Prepared by Hatch Associates Ltd.: principal consultant, T.J. Robinson. Ottawa: Canada Mortgage and Housing Corp., 1984.

TH 7011 R6 — Robitaille, Ludger et Belisle, Louis A. Chauffage et ventilation. Arts, métiers et technique. Québec, Québec: Bélisle; Société canadienne de technologie, 1948.

Cal MH 84C20 — Russell, Peter A.G. and Robinson, Tom D. Carbon Monoxide Poisoning in Housing: Contributing Factors and Remedial Measures. Ottawa: Canada Mortgage and Housing Corporation, 1984.

TH 7222 R87 — Rutkowski, Hank. Residential Equipment Selection. Washington, D.C.: Air Conditioning Contractors of America, 1988.

SW5 IB12 82B23 — Sandberg, Mats; Blomqvist, Claes; and Sjoberg, Mats. Warm Air Systems: Part 2: Tracer Gas Measurement and Ventilation Efficiencies. Report no. M8223. Gavle, Sweden: Statens institut för byggnadsforskning, 1982.

Cal MH 89D28 — Scanada Consultants Ltd. Developmental Version of the Roofdry Model: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1989.

TH 7684 D9F7 1983 — _____. First Trials of Comprehensive Airtightening of Existing Houses. Prepared for Canada Mortgage and Housing Corporation. Ottawa: Scanada, 1983.

Cal MH 88F47 _____. Flue Simulator: Version 4.2: User's Manual. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH110 87I52 _____. The Influence of Flue Dampers on the Venting Performance of Flues. A study prepared for Canada Mortgage and Housing Corporation by Scanada Consultants Limited, Scanada Sheltair Consortium Inc.; principal consultants: John C. Haysom, Robin P. Sinha. Ottawa: The Corporation, 1987.

Cal MH110 87I53 _____. The Influence of Flue Sharing on Venting Performance. A study prepared for Canada Mortgage and Housing Corporation by Scanada Consultants Limited, Scanada Sheltair Consortium Inc.; principal consultants: John C. Haysom, Michael C. Swinton. Ottawa: The Corporation, 1987.

Cal MH110 87I57 _____. The Influence of Termination Configuration on the Flow Performance of Flues. A study prepared for Canada Mortgage and Housing Corporation by Scanada Consultants Limited, Scanada Sheltair Consortium Inc.; principal consultants: John C. Haysom, Michael C. Swinton. Ottawa: The Corporation, 1987.

Cal MH110 87R23 _____. Residential Combustion Venting Failure: A Systems Approach: Final Technical Report prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation; prepared by Scanada Sheltair Consortium. Ottawa: The Division, 1987. 13 volumes.

Cal MH110 87R24 _____. Residential Combustion Venting Failure: A Systems Approach: Summary Report prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation; prepared by Scanada Sheltair Consortium. Ottawa: The Division, 1987.

Cal MH110 87S72 _____. Study of Flue Parameters Affecting Backdrafting and Spillage. A study prepared for Canada Mortgage and Housing Corporation by Scanada Consultants Limited, Scanada Sheltair Consortium Inc. and G.K. Yuill and Associates Ltd. Ottawa: The Corporation, 1987.

Cal MH65 85T31 ———. Thermal and Aerodynamic Performance of Chimney Flues: Armstrong House Field Testing Phase 1 and 2 prepared for Canada Mortgage and Housing Corporation, Project Implementation Division. Ottawa: The Division, 1985.

Cal IA 85I53 Semchuk, B. Improved Heating and Ventilating Distribution Techniques. Ottawa: Indian and Northern Affairs Canada, 1985.

Cal MH110 89C16 Sheltair Consultants Ltd. The Canadian Residential Duct and Chimney Survey. Ottawa: Canada Mortgage and Housing Corporation, 1989.

Cal MH110 87C37 Sheltair Scientific Ltd. Chimney Safety Tests Users' Manual: Procedures for Determining the Safety of Residential Chimneys. Prepared for Research Division, Canada Mortgage and Housing Corporation; prepared by Sheltair Scientific Ltd., Scanada-Sheltair Consortium Inc. Ottawa: The Division, 1987.

Cal MH110 88C37 ———. Chimney Safety Tests User's Manual: Procedures for Determining the Safety of Residential Chimneys. 2nd edition. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH110 88D77 ———. Duct Test Rig: the Development and Evaluation of a Device for Testing Residential Ducts, Vents, and Chimneys: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal MH110 87M51 ———. Monitoring Combustion Gas Spillage Frequency and Duration in 20 Problem Prone Houses: Final Report. Prepared for Research Division, Canada Mortgage and Housing Corporation. Ottawa: The Division, 1987.

Cal MH110 87P27 ———. The Performance of Sealed and Insulated Venting Systems in Combination with High Pressure Oil Burners. Prepared for Research Division, Canada Mortgage and Housing Corporation. A study prepared by Sheltair Scientific Ltd., Scanada-Sheltair Consortium Inc., principal consultant: Sebastian Moffatt. Ottawa: The Division, 1987.

Cal MH110 89P62 ———. A Procedure for Determining Airtightness Characteristics of Attic Spaces: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1989.

TH 7684 D9R47 1984 ———. Residential Chimney Backdraft Checklist: Design and Evaluation prepared for Resource and Research Management Division, Canada Mortgage and Housing Corporation. Vancouver, B.C.: Sheltair Scientific Ltd., 1984.

Cal MH110 85R23 ———. Residential Combustion Safety Checklists. A report prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation. Principal consultant: Sebastian Moffatt. Ottawa: The Division, 1985.

TH 7684 D9S53 1981 Sherman, M.H.; Modera, M.P.; and Grimsrud, D.T. A Predictive Air Infiltration Model: Field Validation and Sensitivity Analysis. Berkeley, CA: Energy Performance of Buildings Program, Lawrence Berkeley Laboratory, University of California; Springfield, VA: National Technical Information Service, 1981.

TH 7684 D9S54 1984 Sherman, M.H.; Wilson, D.J. and Kiel, D.E. Variability in Residential Air Leakage. Berkeley, CA: Applied Science Division, Lawrence Berkeley Laboratory: Springfield, VA: National Technical Information Service, 1984.

TJ 263 S48 1982 Shurcliff, W.A. Air-to-air Heat Exchangers for Houses: How to Bring Fresh Air Into Your Home and Expel Polluted Air, While Recovering Valuable Heat. Andover, Mass,: Brick House Pub. Co., 1982.

TH 1715 S519 1988 ———. Super Insulated Houses and Air to Air Heat Exchangers. Andover, Mass.: Brick House Publishing Company, 1988.

TH 7684 D9S55 1984 Simoneau, Jacques. Effet de l'orientation d'une résidence type sur le taux d'infiltration d'air. Thèse (Maître en Sciences) - Université Laval, 1984.

Cal MH65 89C05 Sinha, R.P. and Duncan, R.L. CMHC/EMR Northern Initiatives: R-2000 Home Program Technology Project, Northwest Territories Housing Corporation Technical Support. Ottawa: Canada Mortgage and Housing Corporation, 1989.

Cal MH110 83I51 Small, Bruce. Indoor Air Pollution and Housing Technology. Prepared for the Planning Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation; by Bruce M. Small and Associates Limited; principal consultant, Bruce M. Small; CMHC project manager, Judy Lorimer; CMHC technical adviser, Peter Russell. Ottawa: CMHC, 1983.

Cal MH 87M51f Société canadienne d'hypothèques et de logement. L'air et humidité: Problèmes et solutions. Ottawa: La Société, 1987.

Cal MH 86V23f _____. La ventilation: santé et sécurité: problèmes, causes et solutions. Ottawa: La Société, 1986.

SW5 BR20 83D07 Södergren, David, and Puntilla, Antero. A CO2-controlled Ventilation System: Pilot Study. Stockholm: Swedish Council for Building Research, 1983.

TH 7684 D9S64 1985 Solplan 6: An Air Exchanger for Energy Efficient Well Sealed Houses. North Vancouver, B.C.: Drawing-Room Graphic Services, 1985.

Cal MT259 84R01 Sulatisky, M.T. Airtightness Tests on 200 New Houses Across Canada: Summary of Results: An Investigation of the Levels of Airtightness in New Canadian Housing, Including Regional Variations: A Research Report sponsored by the Energy Conservation and Oil Substitution Branch, Energy, Mines and Resources Canada. Report no. 84.01. Ottawa: BETT, 1984.

US1 DE84 79S48 Summer Attic and Whole-House Ventilation Workshop, Gaithersburg, Md., 1978. Summer Attic and Whole-house Ventilation: Proceedings of a workshop held July 13, 1978, at the National Bureau of Standards, Gaithersburg, Maryland. Edited by Mary H. Reppert. Co-sponsored by the Department of Energy and the attic ventilation industry. NBS Special Publication; 548. Washington: U.S. Dept. of Commerce, National Bureau of Standards, 1979.

SW5 IB12 83B11 Svensson, Anders. Methods for Measurement of Airflow Rates in Ventilation Systems. Stockholm: National Swedish Institute for Building Research, 1983.

SW5 PB 82A36 Sweden. Air Quality: Chapter 36 of Swedish Building Code SBN 1980. English translation by L.J. Gruber. Stockholm: National Board of Physical Planning and Building, 1982.

SW5 PB 82T32 Sweden. Thermal Insulation and Airtightness: Chapter 33 of Swedish Building Code SBN 1980. Stockholm: National Board of Physical Planning and Building, 1982.

SW5 PB 82T33 Sweden. Thermal Internal Climate: Chapter 35 of Swedish Building Code SBN 1980. English translation by L.J. Gruber. Stockholm: National Board of Physical Planning and Building, 1982.

Cal MH305 80R28 TES Limited. A Review of Ventilation Requirements for Residential Buildings in Canada. Prepared for Canada Mortgage and Housing Corporation, Technical Research Division by TES Limited. TES Report no: C289-1. Ottawa: The Corporation, 1980.

Cal MT259 83R04 _____. Ventilation Requirements for Airtight Homes: A Research Report: A Summary of Ventilation Requirements for Airtight Homes in Canada. Prepared under a sub-contract from Engineering Sciences Division, Ontario Research Foundation. BETT publication; no.83.04. Ottawa: Buildings Energy Technology Transfer Program, Energy, Mines and Resources Canada, 1983, 1984.

TH 7015 T36 no.8 Thompson, Catriona. A Subject Analysis of the AIC's Bibliographic Database: AIRBASE. Technical note AIC-TN-8-82. 2nd ed. Bracknell, Eng.: Air Infiltration Centre, 1982.

Cal PW22 88D09 Tilley, B. Air Circulation Evaluation. Ottawa: Public Works Canada, Architectural and Engineering Services, 1988.

Cal PW22 88D09 _____. Évaluation de la circulation de l'air. Ottawa: Travaux publics, Services d'architecture et de génie, 1988.

Cal
MT259
85R04
Timothy Mayo Communications. Residential Ventilation Requirements: A Research Report. Sponsored by the Energy Conservation Branch, Energy, Mines and Resources Canada; prepared under a sub-contract from the Saskatchewan Research Council. Ottawa: Building Energy Technology Transfer Program, Energy, Mines and Resources Canada, 1985.

TH
7406
T55
1986
Timusk, J.; Selby, K.A.; and Seskus, A.L. Consumers' Gas Chimney Venting Performance Study. Sponsored by BETT, Energy, Mines and Resources Canada and Ontario Ministry of Energy. S.l. : s.n., 1986.

Cal
MH65
87P22
Timusk, J.; Seskus, A.L.; and Lio, M. Performance Evaluation of the Dynamic Wall House. Prepared for Project Implementation Division, Canada Mortgage and Housing Corporation by Centre for Building Science, University of Toronto. Ottawa: The Corporation, 1987.

Cal
PW22
88D37f
Travaux Publics Canada. Mesure de la vitesse d'échange d'air extérieur. Ottawa: Travaux Publics, Services d'architecture et de génie, 1988.

TH
7684
D9T73
1986
Trepte, Lutz and Le Marie, André. Research on Air Infiltration, Ventilation and Indoor Air Quality in the Federal Republic of Germany: Report. Friedrichshafen, Germany: L. Trepte, 1986.

Cal
MH
89C62
Trow, Inc. Criteria for the Air Leakage Characteristics of Building Envelopes: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1989.

RA
575.5
T87
1985
Turiel, Isaac. Indoor Air Quality and Human Health. Stanford, Calif.: Stanford University Press, 1985.

US1
EM
79A78
Turiel, Isaac; Hollowell, Craig D. and Thurston, Benjamin E. Automatic Variable Ventilation Control Systems Based on Air Quality Detection. LBL-8893; EEB Vent 79-3. Berkeley: Energy and Environment Division, Lawrence Berkeley Laboratory, University of California; Springfield, Va.: National Technical Information Service, 1979.

Cal MH 88C05 — Unies Ltd. CMHC Guide to Ventilation Systems: Consumer's Series. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Ca6 RA 83E82 — _____. An Evaluation of the Effectiveness of Air Leakage Sealing: Ener-Corp Management Ltd. Ottawa: Energy, Mines and Resources Canada; Winnipeg: Manitoba Dept. of Energy and Mines, 1983.

US1 GA 80I51 — United States. General Accounting Office. Indoor Air Pollution: An Emerging Health Problem: Report to the Congress. By the Comptroller General of the United States. Washington, D.C.: U.S. General Accounting Office, 1980.

TH 7225 V35 — Van Straaten, J.F. Thermal Performance of Buildings. Elsevier Architectural Service Series. Amsterdam; New York: Elsevier Publication Co., 1967.

US1 ER41 86R16 — United States. Environmental Protection Agency. Research and Development. Radon Reduction Methods: A Homeowner's Guide. Washington: Environmental Protection Agency, Research and Development, 1986.

Ref. Z 5941 V3 no.1590 — Vance, Mary. Ventilation: A Bibliography. Architecture series; Bibliography, A-1590. Monticello, Ill.: Vance Bibliographies, 1986.

TH 7684 D9V46 1984 — La Ventilation dans l'habitat existant. Réalisé par le Centre d'assistance technique et de documentation avec le concours de Électricité de France, Direction de la distribution. Paris: Publications du Moniteur, 1984.

US2 NN ER5 85R10 — W.S. Fleming and Associates. Indoor Air Quality, Infiltration and Ventilation in Residential Buildings: Final Report prepared for New York State Energy Research and Development Authority and Niagara Mohawk Power Corporation. Albany, N.Y.: NYSERDA, 1985.

TD 883.5 C2W33 1982 — Wagner, Barbara Shohl. Residential Indoor Air Quality-Air Infiltration Study. Berkeley, California: Lawrence Berkeley Laboratory, University of California, Applied Science Division: Springfield, Va.: National Technical Information Service, 1982.

TH 7684 D9W57 1984 — White, Jim H. Separation of Combustion and Ventilation Air. Jim H. White, CMHC Research Division to Canadian Gas Association Marketing Conference, Winnipeg 1984. [S.l.: s.n.] 1984

Cal MH110 84S76 — _____. A Summary of Questions Asked at NRC's Building Science Insight '83: Humidity, Condensation and Ventilation in Houses. Prepared by J.H. White of Canada Mortgage and Housing Corporation, Research Division, as a service to the National Research Council of Canada, Division of Building Research. Ottawa: Canada Mortgage and Housing Corporation, 1984.

Cal MH 84V21 — _____. Ventilation Compliance Tests for Houses. Ottawa: Canada Mortgage and Housing Corporation, 1984.

Cal MH 84V23 — _____. Ventilation for Humidity Control: A Research Report. Ottawa: Canada Mortgage and Housing Corporation, 1984.

TH 7653 W48 1986 — Whittle, Geoffrey E. Room Air Distribution: Design and Evaluation. Bracknell, Berkshire: Building Services Research and Information Association, 1986.

TH 7684 D9W58 — Wilson, Alex. Contractor's Guide to Finding and Sealing Hidden Air Leaks. Lincoln, Mass.: Environmental Science Dept., Massachusetts Audubon Society, 198-.

Cal MH 82C54 — Wood, Leonard Alfred. CMHC Monitoring Armstrong Upgraded Houses: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1982.

Cal MH 88W54 — Woodfire '88: Handout for the CMHC/EMR/CWEI Seminar on the Science of Venting Woodstoves and Fireplaces in Modern Housing. Ottawa: Canada Mortgage and Housing Corporation, 1988.

Cal
MH110
81T22

Yuill, G.K. Technological Evaluation of the Pressure Pulse Method of Airtightness Testing as an Alternative to the Blower Door Technique Report. Prepared for the Technical Research Division, Policy Development and Research Sector of Canada Mortgage and Housing Corporation, by Lion Industries. Ottawa: CMHC, 1981.

Prepared at:
Canadian Housing Information Centre
Canada Mortgage and Housing Corporation
Ground Floor, Building C
700 Montreal Road
Ottawa, Ontario
K1A OP7

Préparé au:
Centre canadien de documentation sur l'habitation
Société canadienne d'hypothèques et de logement
Rez-de-chaussée, édifice C
700, chemin Montréal
Ottawa, Ontario
K1A OP7

Rev. September/septembre 1991.